

Project:
Chemung County Run
Off Project

Site Contractor:
Chemung County Soil &
Water

Product:
LondonBoulder w/ Field
Stone Face

Manufacturer:
Zeiser Wilbert Vault
Elmira NY

The Challenge:

In this particular residential area the residents had long had a run off spillway moving through many of their backyards. This run off took all the water from the above hillside and redirected it toward the Chemung County River. The old wall was built with rip rap and over many years the surrounding soils began to erode and many of the lawns started to slide into the run off bed. Jimmie Joe Carl and Mark Watts approached us to inquire about replacing the wall using our LondonBoulder system.

They really like the natural stone look and how you could build multiple radius points with this system. They spent a few weeks excavating the old rip rap out and replacing it with two courses of full block stone and one course of the sod cap block.

The surrounding neighbors really loved the end result and were very pleased to see that they had their backyards restored to what they knew it to be in years past.

